

# SAFETY RECALL NOTICE

## Metalux Fluorescent Shoplight

Model # 9240



**COOPER** Lighting



If the two prongs on the plug's electrical cord are touched simultaneously while the lamps are installed, the light can present an electric shock hazard to consumers.

**If you purchased the 9240 Shoplight since Jan. 1, 2007:**

- 1) Identify the Model number 9240 (Fig. 1) and Date Code (Fig. 2).

Date Code range subject to recall: 335 06 (Dec. 1, 2006) to 257 07 (Sept. 14, 2007).

- 2) If the Date Code falls within the above range, **IMMEDIATELY** discontinue use and continue on to the following instructions.
- 3) Unplug product – **DO NOT** come into contact with prongs on plug (Fig. 3).
- 4) Allow bulbs to cool and remove them.
- 5) Uninstall product and return to place of purchase for refund or credit.



Contact Cooper Lighting from  
8AM – 5PM ET, M-F at:

**(800) 440-1676**

or visit their website at:

[www.cooperlighting.com](http://www.cooperlighting.com)